

Do not overtighten the End Nuts. This will cause damage to the High Pressure Piston inside the pump. Fix leaks the right way, by cleaning the End Washer or by replacing o-rings.

